We Think For You

## ARCHITECTS, ENGINEERS & INTERIOR DESIGNERS

PLANNING, VASTU DESIGN, INTERIOR DESIGN, 3D-DESIGN, STRUCTURAL DESIGN, LANDSCAPE, ESTIMATION, CONSULTANT

Memo No: - 23/April Date: - 28/04/2023

## **TO WHOM IT MAY CONCERN**

Certificate of conformity to regulation and structural safety of school building.

## Details of the building for which the certificate is being issued.

Name of School	BLJ DAV Centenary Public School
Location	Jakhal Mandi, Distt. Fatehabad, (Haryana)
Run By	DAV College Managing Committee, New Delhi

## **CERTIFICATE**

I have inspected the school building of above mentioned school on dated 27/04/2023. Structure of the school building is in good condition. Brick walls are constructed with cement mortar and roofs are of R.C.C. slab. All the rooms are well ventilated and airy. Floors are constructed with first class material. School building falls in seismic Zone-III. Structure of school building (i.e. foundation, column, beam, etc) is designed as per IS codes with considering all kind of load combinations.

The building of school is found in safe and sound condition.

Er. Navdeep Kumar

Structure Engineer Regd. With (Haryana Shehri Vikas Pradhikaran) License No. 26 ER. NAVDEEP KUMAR B.Tech (Civil Engg.) M.Tech (Structure Engg.) M. - 9896882499

**Engineer Sign/Stamp** 

Owner Sign